

service bulletin

M81-26

Technical Portions are
FAA-DER Approved

4 December, 1981

TO: Aircraft Manufacturers, Distributors, Dealers, Engine Overhaul Facilities,
Owners and Operators of Teledyne Continental Motors' Aircraft Engines.

SUBJECT: PRESSURIZATION OF MAGNETOS IN MOONEY M20K AIRCRAFT

MODELS

AFFECTED: TSIO-360GB Spec. 1 & 3 Engines.

Gentlemen:

For improved altitude performance, we recommend that owners of TSIO-360GB engines equipped with Bendix S6RN-20 magnetos install the pressurization kit EQ6565 in accordance with Figure 1.

Bendix Service Bulletin 612 should also be complied with at this time.

Installations with Slick Magnetos can be pressurized using kit EQ6569 in accordance with Figure 2. Reset timing in accordance with instructions in Overhaul Manual form X30030A.

Reference Mooney Service Instruction M20-58 for airframe installation information.

Pressurization kits EQ6565 and EQ6569 are available only through the Mooney distributor organization.




FIGURE 1




FIGURE 2