

TELEDYNE CONTINENTAL[®] AIRCRAFT ENGINE
SERVICE INFORMATION LETTER
Contains Useful Information Pertaining To Your Aircraft Engine

CATEGORY 5

SIL06-3

Technical Portions FAA
 Approved

SUBJECT: CRANKSHAFT GEAR RETAINING SCREW

PURPOSE: To announce the supersedure of P/N 536379 crankshaft gear retaining screw by P/N 656990 retaining screw.

MODELS

AFFECTED: O-470-Series; IO-346-A; IO-470-Series; IO-520-Series; LIO-520-P; IO-550-Series
 IOF-550-Series; TSIO-470-B, C and D; L&TSIO-520-Series; TSIO-550-A, B, C and E;
 TSIOL-550-A, B and C; GTSIO-520-Series

Teledyne Continental Motors (TCM) has announced the release of a new crankshaft gear retaining screw (bolt) P/N 656990 for the above listed engines. Retaining screw P/N 536379 is no longer available.

The new P/N 656990 retaining screw may be obtained through any TCM authorized distributor. To locate your nearest TCM authorized distributor you may go on-line to:

www.tcmlink.com/distributor/distributorLocator.cfm

OR

Call TCM Customer Service at 1-888-826-5465 or 1-251-438-3411 Extension 8292.

ISSUED			REVISED			 Teledyne Continental Motors, Inc. <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		1 of 1	
04	28	2006				SIL06-3		